

# Intel<sup>®</sup> Omni-Path Fabric Software

Version 10.0.0 Release Notes

---

*March 2016*



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.


Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or by visiting: <http://www.intel.com/design/literature.htm>

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at <http://www.intel.com/> or from the OEM or retailer.

Intel, Xeon, and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2015-2016, Intel Corporation. All rights reserved.



## Contents

---

<b>1.0 Overview of the Release</b>	4
1.1 Introduction	4
1.2 Audience	4
1.3 Software License Agreement	4
1.4 If You Need Help	4
1.5 New Features in this Release	4
1.6 Supported Features	5
1.7 Release Packages	5
1.8 Operating Systems	6
1.9 Parallel File System	6
1.10 Compilers	7
1.10.1 MPI	7
1.10.2 MVAPICH2 and Open MPI	7
1.11 Hardware	8
1.12 Installation Requirements	8
1.12.1 Software and Firmware Requirements	8
1.12.2 Installation Instructions	8
1.13 Product Constraints	9
1.14 Product Limitations	9
1.15 Documentation	9
<b>2.0 Issues</b>	11
2.1 Introduction	11
2.2 Resolved Issues	11
2.3 Open Issues	12
<b>Tables</b>	
1-1 Operating Systems Supported	6
1-2 MPI Compilers	7
1-3 MVAPICH2 and Open MPI	7
1-4 Hardware Supported	8
1-5 Related Documentation for this Release	10
2-1 Resolved Issues	11
2-2 Open Issues	12

## S



## 1.0 Overview of the Release

---

### 1.1 Introduction

This document provides a brief overview of the changes introduced into the Intel® Omni-Path Software by this release. References to more detailed information are provided where necessary. The information contained in this document is intended as supplemental information only; it should be used in conjunction with the documentation provided for each component.

These Release Notes list the features supported in this software release, open issues, and issues that were resolved during release development.

### 1.2 Audience

The information provided in this document is intended for installers, software support engineers, service personnel, and system administrators.

### 1.3 Software License Agreement

This software is provided under license agreements and may contain third-party software under separate third-party licensing. Please refer to the license files provided with the software for specific details.

### 1.4 If You Need Help

Technical support for Intel® Omni-Path products is available 24 hours a day, 365 days a year. Please contact Intel Customer Support or visit [www.intel.com](http://www.intel.com) for additional detail.

### 1.5 New Features in this Release

The following features are new for the 10.0.0 release:

- Additional operating systems supported. See [Table 1-1](#) for details.
- Additional hardware supported. See [Table 1-4](#) for details.
- MPI applications are provided in a stand-alone rpm package.
- Intel® Xeon® v4 processor (codename Broadwell) support
- KNL support (B0 technology preview)
- In-band PXE boot over Intel® Omni-Path
- New document *Intel® Omni-Path Storage Router Design Guide*, see [Table 1-5](#).
- Monitored Intel® Omni-Path Host Fabric Interface
- DHCP and LDAP supported on Intel® Omni-Path Edge Switch 100 Series and Intel® Omni-Path Director Class Switch 100 Series hardware.



## 1.6 Supported Features

- The list of supported operating systems is in [Table 1-1](#).
- The list of supported hardware is in [Table 1-4](#).
- Coexistence with Intel® True Scale Architecture. This release supports True Scale hardware serving as an Infiniband\* storage network with the Intel® Omni-Path hardware used for computing. Note that connecting a True Scale adapter card to an Omni-Path switch, or vice-versa, is not supported. For more details on this feature, refer to *Intel® Omni-Path Fabric Host Software User Guide*.
- Supports Dual Rail: Two Intel® Omni-Path Host Fabric Interface (HFI) cards in the same server connected to the same fabric.
- Supports Dual Plane: Two HFI cards in the same server connected to separate fabrics.
- Limited validation testing performed on network storage file systems:
  - NFS over TCP/IP
  - GPFS
- Active Optical Cables
- Intel® Omni-Path Boot over Fabric

## 1.7 Release Packages


There are two Intel® Omni-Path Fabric Software packages:

- Basic for compute nodes
- IFS for the management node

The Basic package includes:

- Software that installs the following packages to the distribution OpenFabrics Alliance\* (OFA):
  - libibumad is based on the RHEL\* or SLES\* release package. It contains Intel patches that support Intel® Omni-Path Architecture (Intel® OPA) technology.
  - ibacm is the latest upstream code applied with RHEL\* patches.
  - hfi1-firmware, hfi1-psm, hfi1-diagtools-sw, libhfi1verbs
  - Open MPI built for verbs and PSM2 using gcc, Intel, and PGI compilers.
  - MVAPICH2 built for verbs and PSM2 using gcc, Intel, and PGI compilers.
  - mpitests
  - mpi-selector
  - GASnet
  - openSHMEM
  - srptools (includes the latest upstream code)
  - Firmware files listed in the following table.

Description	File Name	Version
Intel® Omni-Path Boot over Fabric	hfi1_fabric_boot_7.rom	v1.8
HFI1 UEFI Option ROM	HfiPcieGen3_9.rom	0x14
HFI SMBus Microcontroller Temperature Sensor	hfi1_smbus.fw	10.0.0.0.696



- compat-rdma which delivers kernel changes based on the OFA version. The components installed are the hfi1 driver and Intel-enhanced versions of other kernel packages. See the *Intel® Omni-Path Fabric Software Installation Guide* for details.

**Note:** In the Intel® Omni-Path Software package for RHEL\* 7.2, the hfi1 driver and ifs-kernel-updates are supplied as a smaller package.

The IFS package includes the Basic package plus:

- Fabric Manager, which allows comprehensive control of administrative functions using a mature Subnet Manager. Fabric Manager simplifies subnet, fabric, and individual component management, easing the deployment and optimization of large fabrics.
- Fabric Suite FastFabric Toolset, which enables rapid, error-free installation and configuration of Intel® OPA host software and management software tools, as well as simplified installation, configuration, validation, and optimization of HPC fabrics. For details, refer to the Fabric Suite FastFabric documentation in [Table 1-5](#).

## 1.8 Operating Systems

This release of the Intel® Omni-Path Software supports the operating systems listed in [Table 1-1](#).

**Table 1-1. Operating Systems Supported**

Operating System	Update/SP	Kernel Version
Red Hat* Enterprise Linux* (RHEL*) 7.1 X86_64	Update 1	3.10.0-229.el7.x86_64
CentOS* 7.1 X86_64	N/A	3.10.0-229.el7.x86_64
Scientific Linux* 7.1 X86_64	N/A	3.10.0-229.el7.x86_64
Red Hat* Enterprise Linux* (RHEL*) 7.2 X86_64	Update 2	3.10.0-327.el7.x86_64
SUSE* Linux* Enterprise Server (SLES*) 12 X86_64	N/A	3.12.28-4-default
SUSE* Linux* Enterprise Server (SLES*) 12.1 X86_64	Service Pack 1	3.12.49-11.1-default

## 1.9 Parallel File System

The following parallel file system has been tested with this release of the Intel® Omni-Path Software:

- IBM\* General Parallel File System (GPFS) version 4.0.1
  - RHEL\* 7.1 and 7.2

Refer to the *Intel® Omni-Path Fabric Host Software User Guide* for details on optimizing parallel file system performance with Intel® Omni-Path Software.



## 1.10 Compilers

### 1.10.1 MPI

This release supports the following MPI implementations:

**Table 1-2. MPI Compilers**

MPI Implementation	Runs Over	Compiled With
Open MPI 1.10.0	Verbs	GCC
	PSM2	GCC, Intel
MVAPICH2-2.1	Verbs	GCC
	PSM2	GCC, Intel
Intel® MPI 5.1.2	Verbs	GCC
	PSM2	GCC, Intel

### 1.10.2 MVAPICH2 and Open MPI

MVAPICH2 and Open MPI have been compiled for PSM2 to support the following versions of the compilers:

**Table 1-3. MVAPICH2 and Open MPI**

Compiler	Linux* Distribution	Compiler Version
(GNU) gcc	RHEL* 7	gcc (GCC) 4.8.2 20140120
(GNU) gcc	RHEL* 7.1	gcc (GCC) 4.8.3 20140911
(GNU) gcc	RHEL* 7.2	gcc (GCC) 4.8.5 20150623 (Red Hat* 4.8.5-4)
(GNU) gcc	SLES* 12	gcc (SUSE* Linux*) 4.8.3 20140627
(GNU) gcc	SLES* 12 SP 1	gcc (SUSE* Linux*) version 4.8.5
(Intel) icc	RHEL* 7	icc (ICC) 15.0.1
(Intel) icc	RHEL* 7.1	icc (ICC) 15.0.1
(Intel) icc	RHEL* 7.2	icc (ICC) 15.0.1
(Intel) icc	SLES* 12	icc (ICC) 15.0.1
(Intel) icc	SLES* 12 SP 1	icc (ICC) 15.0.1

See ID [132345](#) for expected behavior that may be observed when using Open MPI with the SLURM PMI launcher and PSM2.



## 1.11 Hardware

Table 1-4 lists the hardware supported in this release.

Table 1-4. Hardware Supported

Hardware	Description
Intel® Xeon® v3 Processor	Haswell CPU-based servers
Intel® Xeon® v4 Processor	Broadwell CPU-based servers
Intel® Omni-Path Host Fabric Interface 100HFA016 (x16)	Single Port Host Fabric Interface (HFI)
Intel® Omni-Path Host Fabric Interface 100HFA018 (x8)	Single Port Host Fabric Interface (HFI)
Intel® Omni-Path Switch 100SWE48Q	Managed 48-port Edge Switch
Intel® Omni-Path Switch 100SWE48U	Externally-managed 48-port Edge Switch
Intel® Omni-Path Director Class Switch 100SWD24	Director Class Switch 100 Series, up to 768 ports
Intel® Omni-Path Director Class Switch 100SWD06	Director Class Switch 100 Series, up to 192 ports

## 1.12 Installation Requirements

### 1.12.1 Software and Firmware Requirements

Table 1-1 lists the operating systems supported by this release. Refer to the *Intel® Omni-Path Fabric Software Installation Guide* for the required packages.

### 1.12.2 Installation Instructions

There are two Intel® Omni-Path Fabric Software packages:

- IntelOPA-IFS.<distro>-x86\_64.<version>.tgz for the management node.
- IntelOPA-Basic.<distro>-x86\_64.<version>.tgz for compute nodes.

The packages in the tgz file are RPMs. Installing individual RPMs is not supported in the 10.0.0 release.

Refer to the *Intel® Omni-Path Fabric Software Installation Guide* for related software requirements and complete installation procedures. Refer to the *Intel® Omni-Path Fabric Hardware Installation Guide* for related firmware requirements.

#### 1.12.2.1 Disable SRP Daemon Autostart

By default, RHEL\* 7.1 is configured to autostart the SRP daemon on every node. This daemon performs a fabric search for SRP target devices every minute, which may impact the performance of HPC applications, especially in larger fabrics.

Intel recommends you disable the SRP daemon on all compute nodes and any service nodes. Typically, the SRP daemon only needs to be enabled on filesystem server nodes that are directly accessing block storage devices.

When installing either the IntelOPA-Basic or IntelOPA-IFS packages, there is a prompt: Enable SRP initiator autoload? Intel recommends you use the default option no on all compute nodes and any service nodes.





When installing using other means (such as provisioning systems or direct installation of the rpms), you must manually disable the SRP daemon autostart. After installing the `rdma-*noarch.rpm` package, edit the `/etc/rdma/rdma.conf` file. The default setting is: `SRP_LOAD=yes`. Intel recommends you change this to `no`.

## 1.13 Product Constraints

This release has the following product constraints:

- Do not update HFI UEFI firmware to version 0x14 contained in this release. UEFI version 0x14 may cause a hang condition during boot on servers with BIOS that support UEFI Firmware Management. If this occurs, remove the HFI card from the server and contact Intel Customer Support.

## 1.14 Product Limitations

This release has the following product limitations:

- The UEFI Option ROM and Intel® Omni-Path Boot over Fabric are not signed, and therefore do not support secure boot. In-band PXE boot over Omni-Path (unsecured) is available.
- Short Term History should only be enabled among FMs that are running the same release of software. It should **not** be enabled with FMs running a combination of software releases, for example, release 10.0.0 and pre-production 10.0.0 versions. Prior to starting FMs, short term history files from previous or subsequent software releases should be deleted from the short term history directory:  
`<ShortTermHistory>/<StorageLocation>`  
 FMs running short term history with release 10.0 should also have CPUs that are little-endian.  
 Short Term History is enabled via  
 configuration: `<ShortTermHistory>/<Enable> == 1`
- PA Failover should only be enabled among FMs that are running the same release of software. It should **not** be enabled with FMs running a combination of software releases, for example, release 10.0.0 and pre-production 10.0.0 versions.  
 PA Failover is enabled via  
 configuration: `<PM>/<ImageUpdateInterval> > 0`

## 1.15 Documentation

Table 1-5 lists the end user documentation for the current release.

Documents are available at the following URLs:

- Intel® Omni-Path Switches Installation, User, and Reference Guides  
<http://www.intel.com/SUPPORT/NETWORK/OMNI-SWTCH100/SB/CS-035856.HTM>
- Intel® Omni-Path Host Fabric Interface Installation, User, and Reference Guides (includes software documents)  
<http://www.intel.com/support/network/omni-adptr/sb/CS-035857.htm>
- Drivers and Software (including Release Notes)  
<https://downloadcenter.intel.com/>





Table 1-5. Related Documentation for this Release

Document Title
<b>Hardware Documents</b>
<i>Intel® Omni-Path Fabric Switches Hardware Installation Guide</i>
<i>Intel® Omni-Path Fabric Switches GUI User Guide</i>
<i>Intel® Omni-Path Fabric Switches Command Line Interface Reference Guide</i>
<i>Intel® Omni-Path Edge Switch Platform Configuration Reference Guide</i>
<i>Intel® Omni-Path Fabric Managed Switches Release Notes</i>
<i>Intel® Omni-Path Fabric Externally-Managed Switches Release Notes</i>
<i>Intel® Omni-Path Host Fabric Interface Installation Guide</i>
<b>Fabric Software Documents</b>
<i>Intel® Omni-Path Fabric Software Installation Guide</i>
<i>Intel® Omni-Path Fabric Suite Fabric Manager User Guide</i>
<i>Intel® Omni-Path Fabric Suite FastFabric User Guide</i>
<i>Intel® Omni-Path Fabric Host Software User Guide</i>
<i>Intel® Omni-Path Fabric Suite Fabric Manager GUI Online Help</i>
<i>Intel® Omni-Path Fabric Suite Fabric Manager GUI User Guide</i>
<i>Intel® Omni-Path Fabric Suite FastFabric Command Line Interface Reference Guide</i>
<i>Intel® Performance Scaled Messaging 2 (PSM2) Programmer's Guide</i>
<i>Intel® Omni-Path Fabric Performance Tuning User Guide</i>
<i>Intel® Omni-Path Host Fabric Interface Platform Configuration Reference Guide</i>
<i>Intel® Omni-Path Fabric Software Release Notes</i>
<i>Intel® Omni-Path Fabric Manager GUI Release Notes</i>
<i>Intel® Omni-Path Storage Router Design Guide</i>
<i>Building Lustre* Servers with Intel® Omni-Path Architecture Application Note</i>



## 2.0 Issues

### 2.1 Introduction

This section provides a list of the resolved and open issues in the Intel® Omni-Path Software.

### 2.2 Resolved Issues

Table 2-1 lists issues that are resolved in this release.

**Table 2-1. Resolved Issues**

ID	Component	Description	Resolved in Release
128753	Fabric Management Software/ Fabric Manager	vFabric QoS bandwidth may differ from the configured setting by up to +/- 5%.	10.0.0
129057	Host Fabric Software/ Performance	opapmaquery and other tools report zero or unreliable values for certain host port counters.	10.0.0
130351	Software Installation	Under SLES* 12.0, openmpi components are not installed by default.	10.0.0
130685	HFI Host Driver	Port LED turns ON when the driver loads and a QSFP module is not present.	10.0.0
130849	Management tools	On RHEL* 7.1, opatop output does not display HFI ports in the HFI group.	10.0.0
130862	HFI Host Fabric Software	Per-VL transmit discard counters, for example, XmitDscdV10, always read 0. This error can be seen in seen in hfi1stats or opapmaquery.	10.0.0
130981	Fabric Management Software	The Intel Omni-Path Fabric Manager configuration file (opafm.xml) has the Fabric Executive (FE) disabled by default.	10.0.0
131105	Software Installation	Kernel crash when loading HFI driver with SLES* enabled.	10.0.0
131129	Software Installation	In RHEL* 7.1, the SRP target driver ib_srpt is loaded by default, which is not desired for most non-storage nodes.	10.0.0
131430	Management tools	When using SLES* and all hosts need to be rebooted (for example, for an upgrade), the FastFabric TUI does not reboot the host, even though it says "Passed".	10.0.0
131455	HFI Host Fabric Software	Boot over Fabric support is present in the Beta release, but has not been fully validated to work.	10.0.0
128334	Host Fabric Software/ HFI Host Driver	Under certain high-stress conditions, the driver may become unstable, which may appear as a full or partial hang of the fabric.	10.0.0



## 2.3 Open Issues

Table 2-2 lists the open issues for this release.

**Table 2-2. Open Issues (Sheet 1 of 3)**

ID	Component	Description	Workaround
127520	Host Fabric Software/ MPI/PSM2	A segmentation fault may occur when running MVAPICH2 benchmark jobs utilizing greater than 72 mpi ranks per node.	Set MV2_USE_SHARED_MEM=0 in the MVAPICH2 command line.
129563	HFI Host Fabric Software/ MPI	Memory allocation errors with Mvapich2-2.1/Verbs.	When running mvapich2 jobs with a large number of ranks (for example, between 36 and 72 ranks), you must set the following parameters in /etc/security/limits.conf: * hard memlock unlimited * soft memlock unlimited Also, you must increase the lkey_table_size: LKEY table size in bits ( $2^n$ , $1 \leq n \leq 23$ ) from its default of 16 to 17.
130209	Host Fabric Software/ MPI	Intel® Parallel Studio XE 2016 Composer Edition LD_LIBRARY_PATH causes incompatibility between MPI components.	Revert installation of Intel® Parallel Studio XE 2016 Composer Edition to 2015 version by editing the /root/.bashrc file from: . /opt/intel/bin/iccvars.sh intel64 . /opt/intel/composerxe/bin/compilervars.sh intel64 To: #. /opt/intel/bin/iccvars.sh intel64 . /opt/intel/composerxe/bin/compilervars.sh intel64
130435	HFI Host Driver	Packet traffic stops after reconnecting a Fabric Manager HFI port to a management allowed port that was previously marked "management not allowed".	Reboot the Fabric Manager node.
130791	Host Fabric Software	Using opapacketcapture with large amounts of traffic can cause performance issues on the given host.	Intel recommends you use opapacketcapture on hosts with lower packet rates and bandwidth.
131058	HFI Host Fabric Software	Running a job with Intel® MPI v5.0.2.044 using the OFA fabric (indicated by -IB or I_MPI_FABRICS=ofa) fails to start any test when the number of process ranks requested is greater than 36. The following error is generated: [10] Abort: Got completion with error 12, vendor code=0, dest rank= at line 858 in file ../../../../src/mpid/ch3/channels/nemesis/netmod/ofa/ofa_poll.c	Use one of the following workarounds: • Use Intel® MPI version 5.1.2, which is supported by this OPA Software Release. • Use the TMI fabric to invoke the higher-performing and more reliable PSM2 interface to the OPA hardware.
131176	Host Fabric Software/ MPI	Intel MPI is missing shortcut switch to enable PSM2.	To run PSM2, you must add the following text to the command line: -genv I_MPI_FABRICS tmi -genv I_MPI_TMI_PROVIDER psm2 -genv I_MPI_FALLBACK 0
131646	Host Fabric Software	SRP module works fine on connection setup and data transfer, but hangs on module removal 'modprobe -r ib_srp'.	Contact Intel Customer Support for details.
131651	HFI Host Driver	The UEFI driver cannot be used in combination with BIOS Refresh release for Intel® Xeon® Processor E5 v4 (codename Broadwell).	Intel® Omni-Path boot over fabric capability is not available. Downgrade to an earlier version of BIOS where this feature is required.



**Table 2-2. Open Issues (Sheet 2 of 3)**

ID	Component	Description	Workaround
131745	HFI Host Fabric Software/ MPI	When running OpenMPI 1.10.0 on SLES* 12 with large number of ranks per node (over 40), it may happen that the ORTE daemon (orted) "hangs" during the finalization of job.	Stopping and resuming the "hung" orted process allows the job to finish normally. To find the hung process, run the ps and find a node with several job zombie processes. In that same node, identify the orted process ID and send a stop signal (kill -19 <PID>) and a continue signal (kill -18 <PID>).
131918	HFI Host Fabric Software/ Verbs	Verbs fails with segmentation fault error.	None. or Set piothreshold=0 For instructions, refer to Appendix A in the Intel® Omni-Path Fabric Performance Tuning User Guide.
131934	Fabric Management Software	Redundant FMs may fail to synchronize and may log dbsync errors related to PM history redundancy.	Use the same value for the PM ShortTermHistory.StorageLocation setting in opafm.xml on all redundant FMs.
131947	HFI Host Driver	There is no support for HFI1 counters via: /sys/class/infiniband/hfi1_0/ports/1/counters	Use one of the following methods: <ul style="list-style-type: none"> <li>• Use opainfo to get basic port information.</li> <li>• From a management node, use Intel® FastFabric commands.</li> <li>• Use the Intel® Fabric Manager GUI.</li> </ul>
132062	HFI Host Fabric Software/MPI	When running mpis_stress test with MVAPICH, MVAPICH may fail with "Internal Error" after several hours of execution.	Contact Intel Customer Support for details.
132127	HFI Host Driver	Certain server BIOS does not recognize HFI and fails to appear as a "UEFI Network" in the standard UEFI boot option.	Contact Intel Customer Support for details.
132345	Host Fabric Software/ MPI	When using Open MPI with the SLURM PMI launcher and PSM2, you may see the following error: Error obtaining unique transport key from ORTE (orte_precondition_transports not present in the environment). This is expected behavior. For details, see the Intel® PSM2 Programmer's Guide, in the description of psm2_ep_open() function, unique_job_key parameter.	To resolve this error, set the Open MPI environment variable OMPI_MCA_orte_precondition_transports in every node running the job. The format is 16 digit hexadecimal characters separated by a dash. For example, OMPI_MCA_orte_precondition_transports=13241234acffedeb-abcdefabcdef1233 This key is used by the PSM2 library to uniquely identify each different job end point used on the fabric. If two MPI jobs are running on the same node sharing the same HFI and using PSM2, each one should have a different key.
132506	Management tools	Customers with unique sub-vendor and sub-device IDs experience a failure of the hfi_pkt function in the hostverify.sh script.	Contact Intel Customer Support for details.
132525	Fabric Management/ PM	If you are running in a host subnet manager-embedded subnet manager configuration, a Virtual Fabric cannot run with a MaxMTU value of either 8192 or 10240. This causes checksum errors and forces one of the subnet managers into an inactive state, even though the XML configurations appear to be valid.	Use the setting MaxMTU=Unlimited to achieve higher MTU sizes.



Table 2-2. Open Issues (Sheet 3 of 3)

ID	Component	Description	Workaround
132584	Fabric Management/ FastFabric	FastFabric utility opaswitchadmin shows the status of power supply one (PS1) of unmanaged switch as "N/A" even if it is present and plugged in. It should report "ONLINE" when PS1 is plugged in and "OFFLINE" when it is not.	Query the switch directly with opaswquery using the switch-guid. To read the status of PS1, use the following command: /opt/opa/tools/opaswquery -t <switch-guid> -Q 8 -i 1 To read the status of power supply two (PS2), use opaswitchadmin or use the following command: /opt/opa/tools/opaswquery -t <switch-guid> -Q 8 -i 2
132617	Fabric Management Software/Fabric Manager	Fabric Manager SwitchCascadeActivateEnable configuration setting can leave IPoIB in a non-working state for HFIs. This problem occurs when the Sm.SwitchCascadeActivateEnable setting in opa_fm.xml is enabled for all devices, and the FM is restarted. The restarted SM never issues a client reregistration of SA subscriptions request to endnodes.	Change the default Sm.SwitchCascadeActivateEnable setting in opa_fm.xml to a value of 1, to allow cascade activation of switches only.
132623	Fabric Management/ PM	Due to how the Performance Agent (PA) builds PA responses, a port may exist in one PA query and not in another. This can depend upon several factors, for example: <ul style="list-style-type: none"> <li>PmPortGroup</li> <li>Internal/External membership</li> <li>A possible Performance Manager (PM) Query Failure and/or a possible PM topology failure)</li> </ul>	None. <b>Note:</b> During a sweep if the failed ports count is a non-zero value, some data may be incomplete or missing.
132709	Switch Fabric Management/SM	When running with multiple FMs, the standby FM's PM will have high CPU utilization if running with the PM on, and default settings for ImageUpdateInterval and PM SweepInterval. This behavior is magnified if the standby SM is an ESM, where the console can appear locked up because of the high CPU utilization.	When running in an Host FM environment, this issue will impact only 1 core and is not of concern. When running in an Embedded FM environment, increasing the ImageUpdateInterval to 30 and the PM SweepInterval to 60 will reduce the impact of the issue.
132718	Software Installation	The Intel® Omni-Path SLES 12.1 package contains infiniband-diags version 1.6.4 which does not include the rdma-ndd service.	Install infiniband-diags version 1.6.5.
132760	DC Link Software	Link width downgrade to 0x width on TX [tx 0x0 (0), rx 0xf (4)]	Contact Intel Customer Support for details.
132800	Switch Software/ Chassis Viewer	In Chassis Viewer, FRU information window does not display correct Manufacturer Date and Time information.	Use CLI commands fruInfo or showInventory.
132812	Switch Fabric Management	A GUI-less Linux* install (default option) does not install the bc package which is needed for some Fabric Manager scripts. The issue manifests itself by failing the hfi_pkt test and the log shows: bc command was not found.	Install the bc package.
132903	HFI Host Fabric Software/HFI Host Driver	Packets sit in the highest priority queue for much longer than expected. Error message "user_mad: duplicate packet: both not response" is returned.	Check the IRQ balance. Renice the MAD process to -20.
132937	HFI/HFI Pre-boot software	BIOS with support for UEFI Firmware Management may hang during boot if version 0x14 of the HFI UEFI Option ROM is installed on the HFI card.	Remove the HFI card from the server and contact Intel Customer Support.