

Intel® Modular Server System MFSYS25 Unified Firmware Update Package Contents Matrix

This matrix contains the contents of all Unified Firmware Update (UFU) software packages made available for the MFSYS25 system and will be updated on an ongoing basis.

| UFU Contents | CMM GUI | BIOS | BMC | SAS FW | SAS Option ROM | EBF | Storage IOP | Storage Expander | Storage Redboot | ESM Boot Code | ESM FW | Fan Op Code | Fan Boot Block |
|-----------------|------------------------|-----------------------|--------|------------|----------------|------|-------------|------------------|-----------------|---------------|----------|-------------|----------------|
| P1.0 | 1.0.100.10012007.7372 | SB5000.86B.10.00.0030 | 13.8 | 1.20.00.00 | 6.14.00.00 | 1.2 | 2.91.140.1 | 1.02.140.81 | 1.00.140.52 | 1.0.0.6 | 1.0.0.25 | 1.1 | 1.2 |
| P2.0 | 1.1.100.10302007.8260 | SB5000.86B.10.00.0032 | 1.22.2 | 1.20.00.00 | 6.14.00.00 | 1.2 | 2.91.140.11 | 1.02.140.81 | 1.00.140.52 | 1.0.0.6 | 1.0.0.25 | 1.1 | 1.2 |
| P2.0.5 | 1.1.100.11132007.8633 | SB5000.86B.10.00.0032 | 1.25.1 | 1.20.00.00 | 6.14.00.00 | 1.2 | 2.91.140.11 | 1.02.140.81 | 1.00.140.52 | 1.0.0.6 | 1.0.0.25 | 1.1 | 1.2 |
| P2.0.7 | 1.2.100.01242008.9431 | SB5000.86B.10.00.0035 | 1.27.1 | 1.20.00.00 | 6.14.00.00 | 1.23 | 2.91.140.11 | 1.02.140.81 | 1.00.140.52 | 1.0.0.6 | 1.0.0.25 | 1.1 | 1.2 |
| P2.2.2* | 1.3.100.20080516.11151 | SB5000.86B.10.00.0043 | 1.30.3 | 1.23.07.00 | 6.18.01.00 | 1.24 | 2.91.140.45 | 1.03.0140.01 | 1.01.0140.08 | 1.0.0.6 | 1.0.0.25 | 1.1 | 1.2 |
| P2.2.3** | 1.3.100.20080527.11328 | SB5000.86B.10.00.0043 | 1.30.3 | 1.23.07.00 | 6.18.01.00 | 1.24 | 2.91.140.45 | 1.03.0140.01 | 1.01.0140.08 | 1.0.0.6 | 1.0.0.25 | 1.1 | 1.2 |

Text in Blue indicates a change from the previous release SW stack

Notes:

*The system must be at firmware level P2.07 prior to starting the P2.2.2 update. This release does not support rollback to previous Unified Firmware Update (UFU) packages.

**The system must be at firmware level P2.07 or P2.2.2 prior to starting the P2.2.3 update. This release does not support rollback to previous Unified Firmware Update (UFU) packages.