






**LAND ROVER
PARTS LTD**

FEBRUARY 1991

**MILITARY DEFENDER 110
2.5 DIESEL 12v-12/24volt**
CONTRACT No. LV2A/004



**SUPPLEMENTARY
PARTS
CATALOGUE**



MODEL DEFENDER
BLOCK TS 6170/B

MODULE BL040

BODY JERRYCAN HOLDERS


ILL	PART NO	DESCRIPTION	QTY	REMARKS
1	RRC4134	Door Catch	4	
	RA610253L	Rivet-Door Catch to Door	16	
2	RRC4793	Door Panel LH	1	
3	RRC1726	Support Rubber	2	
	RRC4792	Door Panel RH	1	
	RRC1726	Support Rubber	2	
	RA610373L	Rivet-Fixing Door to Body	14	
4	RRC3977	Outer Support Frame LH	1	
	RRC3976	Outer Support Frame RH	1	
	SF106161L	Screw)Outer Support	5	
	WA106041L	Washer Plain)Frame	5	
	NY106041L	Nyloc Nut)	5	
5	RRC1894	Cross Strap	2	
	SE106161L	Screw)Cross Strap to	2	
	WC106041L	Washer Plain)Bodyside	2	
	WL106001L	Washer Spring)	2	
	WC106041L	Washer Plain)Cross Strap to	4	
	NY106041L	Nyloc Nut)Outer Support	4	
		)Frame		
6	RRC1726	Support Rubber	4	
7	RRC2652	Crossmember	4 1	
	BH108121L	Bolt)Crossmember to	4	
	WL108001L	Washer Spring)Chassis	4	
	WA108051L	Washer Plain)	8	
	NH108041L	Nut)	4	
	SH108201L	Bolt)Crossmember to	4	
	WL108001L	Washer Spring)Floor, Support	4	
	WA108051L	Washer Plain)and Floor	8	
	NH108041L	Nut)support to	4	
		)Chassis		

MODEL DEFENDER
BLOCK TS 6170/B

MODULE BL040

BODY - JERRYCAN HOLDERS - CONTINUED

ILL	PART NO	DESCRIPTION	QTY	REMARKS
8	RRC1909	Sill Panel L.H.	1	
	RRC1908	Sill Panel R.H.	1	
9	RRC3801	Front Support Bracket	2	
10	RRC3803	Mudshield L.H.	1	
	RRC3802	Mudshield R.H.	1	
	SE106161L	Screw)Mudshield to	6	
	WC106041L	Washer Plain)Bodyside	12	
	NY106041L	Nyloc Nut)	6	
11	RRC3805	Floor L.H.	1	
	RRC3804	Floor R.H.	1	
12	RRC3661	Nut Plate	8	
	SH108201L	Bolt)Floor to Front	3	
	WA108051L	Washer Plain)Support Bracket	3	
	WL108001L	Washer Spring)	3	
	NH108041L	Nut)	3	
	SF106161L	Screw)Base of Outer	3	
	WC106041L	Washer Plain)Support Frame	3	
	NY106041L	Nyloc Nut)	3	
13	RRC4306	Security Clip & Chain	4	




TS. 6178/A

MODEL DEFENDER
BLOCK TS 6178/A

MODULE ES030

BODY - SIDE TOOL LOCKER R.H.

ILL	PART NO	DESCRIPTION	QTY	REMARKS
1	FRC4756	Inner Panel RH	1	
2	MUC6324	Seal - Lower Front	1	)
3	MUC1008	Seal - Toolbox Door	1	)To be Cut
4	MWC2567	Seal - Upper Front	1	)to Size
5	MWC2567	Seal - Inner	1	)Required
6	RU612253L	Rivet	10	



TS6178

MODEL DEFENDER
BLOCK TS 6178

MODULE ES030

BODY - SIDE TOOL LOCKER L.H.

ILL	PART NO	DESCRIPTION	QTY	REMARKS
1	RRC4757	Inner Panel LH	1	
2	MUC6324	Seal - Lower Front	1	)
3	MUC1008	Seal - Toolbox Door	1	)To be Cut
4	MWC2567	Seal - Upper Front	1	)to Size
5	MWC2567	Seal - Inner	1	)Required
6	RU612253L	Rivet	10	